Approved For Release 2005/05/20 : CIA-RDP78B04770A001600010019-5

25X1

25X1

25X1

25X1

25X1

25X1

Post Office Box 8043 Southwest Station

Washington, D. C. 20024 REGISTERED 1 3 NOV 1966 letter, dated 10 October 1966, subject: References: 1. "Proposal for a Test Program." 2. Telephone conversation between 25X1 on 1 November 1966. 3. Conference on 3 November 1966 at the Army Map Service between and Government personnel. Gentlemen : Based on an evaluation of the proposal, item 1 above, the Government does not deem it advisable to modify the contract to include additional testing by _____ in that it is considered that sufficient testing has been performed to justify action for correcting deficiencies in the four major areas of concern. These areas are erratic raw stock metering, exposure patterns, alignment of reseau grid, and timing associated with the frame edge detecting system. of the In reference 2 above, 25X1 decision relative to the proposal and also that the Government is currently performing additional testing of the exposure control system and would resume the final acceptance testing upon return of the preview and punch station assembly. It is understood that agreement was reached at the conference on 3 November, reference 3 above, that: will submit a proposal to modify the existing timer associated with the frame edge detecting system, such that it will operate as a function of film displacement. Declass Review by NGA.

Approved For Release 2005/05/20 : CIA-RDP78B04770A001600010019-5

Manager of process of the process of the contract of the process of the contract of the contra

- 2. The subcontractor will modify the preview and punch station assembly to at least include structural rigidity for the film hold-down, alignment of the punches with the macroscope, and to position the punch die in a nominal plane with the film.
- 3. If the proposal for the timer is approved, then corrections to the raw stock metering and exposure patterns will be performed at the Contractor's plant at the time of modifying the timer design; if the proposal is not approved, then the two problem areas will be corrected immediately at the Army Map Service by Contractor personnel.

In the interest of correcting the deficiencies in a timely manner, it is requested that your submission of the proposal be expedited. It is also requested that the preliminary acceptance report on the printer he forwarded as soon as possible.

Very truly yours.

25X1

	10.7 0200, 72000,
	Contracting Officer
	Po.
	By Duly Authorized Representative
Distribution:	
Orig - Addr <u>essce</u>	<u></u>
1 - NPIC	
1 - File	
1 - CAS	
1 - NPIC	
LB/SS/NPIC	(16 Nov 66)

25X1

25X1 25X1